



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Outgoing
C0070039

#4053

K

April 19, 2012

Erwin Sass, General Manager
Canyon Fuel Company, LLC
P.O. Box 1029
Wellington, Utah 84542

Subject: Changes in Water Monitoring, Canyon Fuel Company, LLC, Dugout Canyon Mine, C/007/0039, Task ID #4053

Dear Mr. Sass:

The Division has reviewed your application to revise the water monitoring program at the Dugout Canyon Mine. The Division has identified a deficiency that must be addressed before final approval can be granted. The deficiency is listed as an attachment to this letter.

The initials of the deficiency author are provided so that your staff can communicate directly with that individual should questions arise. The plans as submitted are denied. Please resubmit the entire application.

If you have any questions, please call me at (801) 538-5350.

Sincerely,

Steve Christensen
Permit Supervisor

SKC/ss

cc: Price Field Office

O:\007039.DUG\WG4053\WG4053Def_Ltr.doc



Deficiency List
Task No. 4053
Changes in Water Monitoring

Members of the review team with outstanding deficiencies:
Amanda Daniels (AD)

R645-301-731.210 and -220: The Permittee must provide a commitment that if mining activity is to be expanded towards the water monitoring sites that are designated for elimination, water monitoring activity at those sites would be reinitiated no less than one year prior. (AD)